



Technical

WHEEL SPACING

Products to be conveyed on wheel conveyor should have a smooth and firm bottom to maximize conveyability. It is important to note that wheel conveyor should have a minimum of 5 wheels under smallest box size and a minimum of 3 axles under the package at all times. See "Wheel Patterns" for additional information.

